

Name of Property: THE OWL CLUB OF DENVER (5DV.55428)
City or Vicinity: DENVER
County: DENVER **State:** COLORADO
Photographer: Kathleen Corbett (unless otherwise noted)
Dates Photographed: Exterior, February 24, 2024, (unless otherwise noted)
 Interior, September 21, 2023, (unless otherwise noted)

Exterior Photographs

Photo number	Dir. Facing	Description
		
1	NW	Southeast corner, Owl Club Building

Photo number	Dir. Facing	Description
		
2	W	East side (façade) of Owl Club Building
		
3	SW	Northeast corner


Photo number	Dir. Facing	Description
4	W	
4	W	Narrow space between buildings



Photo number	Dir. Facing	Description	
	5	NW	Glass block windows and primary entrance, façade
	6	SW	Glass block windows and attached planter, façade

Photo number	Dir. Facing	Description
		
7	WSW	Stairwell, north side



Photo number	Dir. Facing	Description	
 A photograph showing the north side of a white, single-story building. The building has a flat roof with a satellite dish and a chimney. A chain-link fence runs along the base of the building. There are trees and bushes in the foreground, and a clear blue sky above.	8	SW	North side of building
 A photograph of a side yard area. A chain-link fence runs across the foreground. To the left is the white building from the previous photo. To the right is a brick building. In the background, there are trees and a clear blue sky. The ground is a mix of grass and snow.	9	W	Side yard

Photo number	Dir. Facing	Description
 A wide-angle photograph showing the north side of a long, white, single-story building. The building has a flat roof with a brick parapet. A series of windows runs along the side. The ground in front is covered with patches of snow and grass. A utility pole with a transformer is visible in the background.	10	SW North side of building
 A closer photograph of a section of the white building. It features a dark blue door and a window with a dark frame. The ground is covered in snow. A fence and trees are visible in the background.	11	SE Stairwell, north side of building



Photo number	Dir. Facing	Description
		
12	S	Detail, north window (second from left), photographed 7/16/2024
		
13	SE	North side of building



Photo number	Dir. Facing	Description
		
14	SE	Cornice (under repair at time of photograph)
		
15	ESE	Northwest corner of building, photographed 9/21/2023

Photo number	Dir. Facing	Description
 A photograph showing the rear of a white, single-story building. The wall is made of white cinder blocks. There is a dark grey door on the right side. To the left of the door, there are two horizontal vents and some electrical conduits and boxes. A small bush is in the foreground on the left.	E	Rear of building, photographed 9/21/2023
 A photograph showing the southwest corner of the white building. A wooden fence runs along the side of the building. In the foreground, there is a green dumpster with graffiti. A ladder is leaning against the building. Power lines and a utility pole are visible in the foreground.	ENE	Southwest corner of building

Photo number	Dir. Facing	Description
	NW	Steel shed (noncontributing), southeast corner
	NNE	Steel shed (noncontributing), southwest corner

Photo number	Dir. Facing	Description
		
20	NW	Site overview, from across Madison Street
		
21	NW	2815 Madison St., with houses on west side of street

Interior Photographs

Photo number	Dir. Facing	Description
 A photograph of an office area. On the left, there is a desk with a chair, a lamp, and some papers. A window with curtains is above the desk. A hallway with red carpeting leads away from the desk. On the right, there is a long wooden counter with a large potted plant behind it. A trash can is under the counter.	See photo key map	Interior, Office area looking toward main room
 A photograph of a front room or lounge. The room has red carpeting and a drop ceiling with recessed lighting. There are two sofas and a coffee table. A large window with a decorative pattern is on the left. A display cabinet is on the right. A leather chair is in the foreground.	See photo key map	Front room



Photo number	Dir. Facing	Description
		
24	See photo key map	Front room, original windows facing stairwell
		
25	See photo key map	Wallpaper mural, front room, in place since at least 1971



Photo number	Dir. Facing	Description
		
26	See photo key map	Wallpaper mural, front room
		
27	See photo key map	Mountain photograph, in place since period of significance





Photo number	Dir. Facing	Description
		 
28, 29, 30	See photo key map	Tuskegee Airman statue by Clarence L. Shivers, in case (28); Detail of associated plaques (29, 30), front room
		
31	See photo key map	Glass block front windows, front room

Photo number	Dir. Facing	Description
		
32	See photo key map	Planter box at entry with owl, front room
		
33	See photo key map	Front room, with Owls R. Washington (L) and D. Newman (R)


Photo number	Dir. Facing	Description
		
		34

Photo number	Dir. Facing	Description
		
35	See photo key map	Library, photographed 9/24/2023, provided by Owl Club of Denver
		
36	See photo key map	Bar, lower level meeting room, photographed 9/24/2023, provided by Owl Club of Denver

Photo number	Dir. Facing	Description
		
37	See photo key map	Lower level, meeting room, photographed 9/24/2023, provided by Owl Club of Denver
		
38	See photo key map	Lower level, kitchen, photographed 7/16/2024